

Duplicate Sample Summary

Client:	Tully Environmental, Inc	SDG No.:	P4856
Project:	Transfer Station-SPDES	Sample ID:	P4840-02
Client ID:	COMPDUP	Percent Solids for Spike Sample:	0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
TSS	mg/L	+/-5	728		734		1	0.82		11/15/2024