

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Matrix:

SOIL

Fax: 908 789 8922

P4860-02

Report of Analysis

Client: Tetra Tech Date Collected: 11/14/24 08:20

Project: Ocean County Landfill 2024 Date Received: 11/14/24

Client Sample ID: PH2-BOT-001 SDG No.: P4860

Lab Sample ID: % Solid: 96.8

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weigl	nt) Prep Date	Date Ana.	Ana Met.
Cyanide	0.61		1	0.045	0.25	mg/Kg	11/15/24 12:20	11/15/24 16:48	9012B
Hexavalent Chromium	0.081	U	1	0.081	0.41	mg/Kg	11/18/24 09:20	11/18/24 15:49	7196A
рН	6.72	Н	1	0	0	pН		11/15/24 17:37	9045D

Comments: pH result reported at temperature 23.4 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits