

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Tetra Tech Date Collected: 11/14/24 10:15

Project: Ocean County Landfill 2024 Date Received: 11/14/24

Client Sample ID: PH2-BOT-007 SDG No.: P4860

 Lab Sample ID:
 P4860-08
 Matrix:
 SOIL

 % Solid:
 98

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weig	ht) Prep Date	Date Ana.	Ana Met.	
Cyanide	0.11	J	1	0.044	0.25	mg/Kg	11/15/24 12:20	11/15/24 16:56	9012B	
Hexavalent Chromium	0.079	U	1	0.079	0.40	mg/Kg	11/18/24 09:20	11/18/24 15:57	7196A	
nЦ	7 2 2	П	1	0	0	nЦ		11/15/24 19:00	0045D	

Comments: pH result reported at temperature 23.0 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits