

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: PSEG Date Collected: 11/18/24 16:30

Project: PSEG 14th-Harts Tice LN UG Date Received: 11/19/24

Client Sample ID: TP-3-WC SDG No.: P4916

Lab Sample ID: P4916-12 Matrix: SOIL

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	5.70	Н	1	0	0	pН		11/19/24 16:30	9045D
Ignitability	NO		1	0	0	oC		11/20/24 11:00	1030
Reactive Cyanide	0.050	U	1	0.0088	0.050	mg/Kg	11/20/24 15:00	11/21/24 11:07	9012B
Reactive Sulfide	3.19	J	1	0.19	10.0	mg/Kg	11/21/24 10:30	11/21/24 15:15	9034

Comments: pH result reported at temperature 24.6 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits