

DATA PACKAGE

GC SEMI-VOLATILES

PROJECT NAME : P.S. 220 - QUEEN

ATC GROUP SERVICES LLC

104 East 25th Street

New York, NY - 10010

Phone No: 212-353-8280

ORDER ID : P4918

ATTENTION : Olga Seldinas



Laboratory Certification ID # 20012



1) Signature Page	3
2) Case Narrative	4
2.1) PCB Group1- Case Narrative	4
3) Qualifier Page	6
4) QA Checklist	7
5) PCB Group1 Data	8
6) Shipping Document	16
6.1) CHAIN OF CUSTODY	17
6.2) Lab Certificate	20

1
2
3
4
5
6

Cover Page

Order ID : P4918

Project ID : P.S. 220 - QUEEN

Client : ATC Group Services LLC

Lab Sample Number

P4918-01
P4918-02
P4918-03
P4918-04
P4918-05

Client Sample Number

ROOF-1-CHIMNEY-GREY
ROOF-1-2A-2B-2C
ROOF-2-3A-3B-3C
EXTERIOR-EXIT-2
ROOM-126

I certify that the data package is in compliance with the terms and conditions of the contract, both technically and for completeness, for other than the conditions detailed above. Release of the data contained in this hard copy data package has been authorized by the laboratory manager or his designee, as verified by the following signature.

Signature : _____

Date: 12/02/2024

NYDOH CERTIFICATION NO - 11376

NJDEP CERTIFICATION NO - 20012

CASE NARRATIVE

ATC Group Services LLC
Project Name: P.S. 220 - QUEEN
Project # N/A
Chemtech Project # P4918
Test Name: PCB Group1

A. Number of Samples and Date of Receipt:

5 Solid samples were received on 11/19/2024.

B. Parameters

According to the Chain of Custody document, the following analyses were requested: PCB Group1. This data package contains results for PCB Group1.

C. Analytical Techniques:

The analyses were performed on instrument GCECD_P. The front column is ZB-MR1 which is 30 meters, 0.32 mm ID, 0.5 um df, Catalogue # 7HM-G016-17. The rear column is ZB-MR2 which is 30 meters, 0.32 mm ID, 0.25 µm; Catalogue # 7HM-G017-11. The analysis of PCB Group1s was based on method 8082A and extraction was done based on method 3541.

D. QA/ QC Samples:

The Holding Times were met for all analysis.

The Surrogate recoveries met the acceptable criteria except for ROOF-1-2A-2B-2C [Tetrachloro-m-xylene(1) - 248%]AS per method one surrogate allowed to fail to meet the criteria per column, No further corrective action was taken.

The Retention Times were acceptable for all samples.

The Blank Spike met requirements for all samples .

The Blank analysis did not indicate the presence of lab contamination.

The Initial Calibration met the requirements .

The Continuous Calibration met the requirements .

E. Additional Comments:

The temperature of the samples at the time of receipt was 20.6°C.

All samples received as Caulk matrix, therefore less volume was taken at the time of extraction.

No MSMSD performed as samples are caulk matrix.

F. Manual Integration Comments:

Please refer to the Manual integration Report included with the Run Logs for information on the manual integrations performed.



284 Sheffield Street, Mountainside, NJ 07092
Phone: 908 789 8900 Fax: 908 789 8922

I certify that the data package is in compliance with the terms and conditions of the contract, both technically and for completeness, for other than the conditions detailed above. The laboratory manager or his designee, as verified by the following signature has authorized release of the data contained in this hard copy data package.

Signature _____

DATA REPORTING QUALIFIERS- ORGANIC

For reporting results, the following “ Results Qualifiers” are used:

Value	If the result is a value greater than or equal to the detection limit, report the value
U	Indicates the compound was analyzed for but was not detected. Report the minimum detection limit for the sample with the U, i.e. “10 U”. This is not necessarily the instrument detection limit attainable for this particular sample based on any concentration or dilution that may have been required.
ND	Indicates the analyte was analyzed for, but not detected
J	Indicates an estimated value. This flag is used: (1) When estimating a concentration for a tentatively identified compound (library search hits, where a 1:1 response is assumed.) (2) When the mass spectral data indicated the identification, however the result was less than the specified detection limit greater than zero. If the detection limit was 10ug/L and a concentration of 3 ug/L was calculated report as 3 J. This is flag is used when similar situation arise on any organic parameter i.e. Pest, PCB and others.
B	Indicates the analyte was found in the blank as well as the sample report as “12 B”.
E	Indicates the analyte ‘s concentration exceeds the calibrated range of the instrument for that specific analysis.
D	This flag identifies all compounds identified in an analysis at a secondary dilution factor.
P	This flag is used for Pesticide/PCB target analyte when there is >25% difference for detected concentrations between the two GC columns. The lower of the two values is reported on Form 1 and flagged with a “P”.
N	This flag indicates presumptive evidence of a compound. This is only used for tentatively identified compounds (TICs), where the identification is based on a mass spectral library search. It applies to all TIC results. For generic characterization of a TIC, such as chlorinated hydrocarbon, the flag is not used.
A	This flag indicates that a Tentatively Identified Compound is a suspected aldol-condensation product.
Q	Indicates the LCS did not meet the control limits requirements

APPENDIX A

QA REVIEW GENERAL DOCUMENTATION

Project #: P4918

Completed

For thorough review, the report must have the following:

GENERAL:

Are all original paperwork present (chain of custody, record of communication,airbill, sample management lab chronicle, login page)

✓

Check chain-of-custody for proper relinquish/return of samples

✓

Is the chain of custody signed and complete

✓

Check internal chain-of-custody for proper relinquish/return of samples /sample extracts

✓

Collect information for each project id from server. Were all requirements followed

✓

COVER PAGE:

Do numbers of samples correspond to the number of samples in the Chain of Custody on login page

✓

Do lab numbers and client Ids on cover page agree with the Chain of Custody

✓

CHAIN OF CUSTODY:

Do requested analyses on Chain of Custody agree with form I results

✓

Do requested analyses on Chain of Custody agree with the log-in page

✓

Were the correct method log-in for analysis according to the Analytical Request and Chain of Custody

✓

Were the samples received within hold time

✓

Were any problems found with the samples at arrival recorded in the Sample Management Laboratory Chronicle

✓

ANALYTICAL:

Was method requirement followed?

✓

Was client requirement followed?

✓

Does the case narrative summarize all QC failure?

✓

All runlogs and manual integration are reviewed for requirements

✓

All manual calculations and /or hand notations verified

✓

QA Review Signature: SOHIL JODHANI

Date: 12/02/2024

Hit Summary Sheet
 SW-846

SDG No.: P4918

Order ID: P4918

Client: ATC Group Services LLC

Project ID: P.S. 220 - QUEEN

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	RDL	Units
Client ID : EXTERIOR-EXIT-2								
P4918-04	EXTERIOR-EXIT-2	CAULK	Aroclor-1254	358		9.50	59.0	ug/kg
Total Concentration:				358.000				
Client ID : ROOM-126								
P4918-05	ROOM-126	CAULK	Aroclor-1254	358	J	80.3	500	ug/kg
Total Concentration:				358.000				



SAMPLE DATA

Report of Analysis

Client:	ATC Group Services LLC		Date Collected:	11/19/24	
Project:	P.S. 220 - QUEEN		Date Received:	11/19/24	
Client Sample ID:	ROOF-1-CHIMNEY-GREY		SDG No.:	P4918	
Lab Sample ID:	P4918-01		Matrix:	CAULK	
Analytical Method:	SW8082A		% Solid:	100	Decanted:
Sample Wt/Vol:	1.59	Units: g	Final Vol:	10000	uL
Soil Aliquot Vol:		uL	Test:	PCB Group1	
Extraction Type:			Injection Volume :		
GPC Factor :	1.0	PH :			
Prep Method :	SW3541B				

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
PP068624.D	1	11/20/24 08:22	11/20/24 13:58	PB165124

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units
TARGETS						
12674-11-2	Aroclor-1016	64.0	U	64.0	321	ug/kg
11104-28-2	Aroclor-1221	121	U	121	321	ug/kg
11141-16-5	Aroclor-1232	64.2	U	64.2	321	ug/kg
53469-21-9	Aroclor-1242	64.0	U	64.0	321	ug/kg
12672-29-6	Aroclor-1248	149	U	149	321	ug/kg
11097-69-1	Aroclor-1254	51.5	U	51.5	321	ug/kg
37324-23-5	Aroclor-1262	86.2	U	86.2	321	ug/kg
11100-14-4	Aroclor-1268	64.7	U	64.7	321	ug/kg
11096-82-5	Aroclor-1260	54.9	U	54.9	321	ug/kg
Total PCBs	Total PCBs	149	U	149	321	ug/kg
SURROGATES						
877-09-8	Tetrachloro-m-xylene	20.1		32 - 144	101%	SPK: 20
2051-24-3	Decachlorobiphenyl	20.6		32 - 175	103%	SPK: 20

Comments:

U = Not Detected	J = Estimated Value
LOQ = Limit of Quantitation	B = Analyte Found in Associated Method Blank
MDL = Method Detection Limit	N = Presumptive Evidence of a Compound
LOD = Limit of Detection	* = Values outside of QC limits
E = Value Exceeds Calibration Range	D = Dilution
P = Indicates >25% difference for detected concentrations between the two GC columns	S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.
Q = indicates LCS control criteria did not meet requirements	() = Laboratory InHouse Limit
M = MS/MSD acceptance criteria did not meet requirements	

Report of Analysis

Client:	ATC Group Services LLC		Date Collected:	11/19/24	
Project:	P.S. 220 - QUEEN		Date Received:	11/19/24	
Client Sample ID:	ROOF-1-2A-2B-2C		SDG No.:	P4918	
Lab Sample ID:	P4918-02		Matrix:	CAULK	
Analytical Method:	SW8082A		% Solid:	100	Decanted:
Sample Wt/Vol:	9.71	Units: g	Final Vol:	10000	uL
Soil Aliquot Vol:			Test:	PCB Group1	
Extraction Type:			Injection Volume :		
GPC Factor :	1.0	PH :			
Prep Method :	SW3541B				

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
PP068625.D	1	11/20/24 08:22	11/20/24 14:15	PB165124

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units
TARGETS						
12674-11-2	Aroclor-1016	10.5	U	10.5	52.5	ug/kg
11104-28-2	Aroclor-1221	19.8	U	19.8	52.5	ug/kg
11141-16-5	Aroclor-1232	10.5	U	10.5	52.5	ug/kg
53469-21-9	Aroclor-1242	10.5	U	10.5	52.5	ug/kg
12672-29-6	Aroclor-1248	24.4	U	24.4	52.5	ug/kg
11097-69-1	Aroclor-1254	8.40	U	8.40	52.5	ug/kg
37324-23-5	Aroclor-1262	14.1	U	14.1	52.5	ug/kg
11100-14-4	Aroclor-1268	10.6	U	10.6	52.5	ug/kg
11096-82-5	Aroclor-1260	9.00	U	9.00	52.5	ug/kg
Total PCBs	Total PCBs	24.4	U	24.4	52.5	ug/kg
SURROGATES						
877-09-8	Tetrachloro-m-xylene	49.7	*	32 - 144	248%	SPK: 20
2051-24-3	Decachlorobiphenyl	33.0		32 - 175	165%	SPK: 20

Comments:

U = Not Detected	J = Estimated Value
LOQ = Limit of Quantitation	B = Analyte Found in Associated Method Blank
MDL = Method Detection Limit	N = Presumptive Evidence of a Compound
LOD = Limit of Detection	* = Values outside of QC limits
E = Value Exceeds Calibration Range	D = Dilution
P = Indicates >25% difference for detected concentrations between the two GC columns	S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.
Q = indicates LCS control criteria did not meet requirements	() = Laboratory InHouse Limit
M = MS/MSD acceptance criteria did not meet requirements	

Report of Analysis

Client:	ATC Group Services LLC		Date Collected:	11/19/24	
Project:	P.S. 220 - QUEEN		Date Received:	11/19/24	
Client Sample ID:	ROOF-2-3A-3B-3C		SDG No.:	P4918	
Lab Sample ID:	P4918-03		Matrix:	CAULK	
Analytical Method:	SW8082A		% Solid:	100	Decanted:
Sample Wt/Vol:	9.25	Units: g	Final Vol:	10000	uL
Soil Aliquot Vol:			Test:	PCB Group1	
Extraction Type:			Injection Volume :		
GPC Factor :	1.0	PH :			
Prep Method :	SW3541B				

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
PP068626.D	1	11/20/24 08:22	11/20/24 14:31	PB165124

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units
TARGETS						
12674-11-2	Aroclor-1016	11.0	U	11.0	55.1	ug/kg
11104-28-2	Aroclor-1221	20.8	U	20.8	55.1	ug/kg
11141-16-5	Aroclor-1232	11.0	U	11.0	55.1	ug/kg
53469-21-9	Aroclor-1242	11.0	U	11.0	55.1	ug/kg
12672-29-6	Aroclor-1248	25.6	U	25.6	55.1	ug/kg
11097-69-1	Aroclor-1254	8.90	U	8.90	55.1	ug/kg
37324-23-5	Aroclor-1262	14.8	U	14.8	55.1	ug/kg
11100-14-4	Aroclor-1268	11.1	U	11.1	55.1	ug/kg
11096-82-5	Aroclor-1260	9.40	U	9.40	55.1	ug/kg
Total PCBs	Total PCBs	25.6	U	25.6	55.1	ug/kg
SURROGATES						
877-09-8	Tetrachloro-m-xylene	21.8		32 - 144	109%	SPK: 20
2051-24-3	Decachlorobiphenyl	22.2		32 - 175	111%	SPK: 20

Comments:

U = Not Detected	J = Estimated Value
LOQ = Limit of Quantitation	B = Analyte Found in Associated Method Blank
MDL = Method Detection Limit	N = Presumptive Evidence of a Compound
LOD = Limit of Detection	* = Values outside of QC limits
E = Value Exceeds Calibration Range	D = Dilution
P = Indicates >25% difference for detected concentrations between the two GC columns	S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.
Q = indicates LCS control criteria did not meet requirements	() = Laboratory InHouse Limit
M = MS/MSD acceptance criteria did not meet requirements	

Report of Analysis

Client:	ATC Group Services LLC	Date Collected:	11/19/24
Project:	P.S. 220 - QUEEN	Date Received:	11/19/24
Client Sample ID:	EXTERIOR-EXIT-2	SDG No.:	P4918
Lab Sample ID:	P4918-04	Matrix:	CAULK
Analytical Method:	SW8082A	% Solid:	100 Decanted:
Sample Wt/Vol:	8.65 Units: g	Final Vol:	10000 uL
Soil Aliquot Vol:	uL	Test:	PCB Group1
Extraction Type:		Injection Volume :	
GPC Factor :	1.0 PH :		
Prep Method :	SW3541B		

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
PP068627.D	1	11/20/24 08:22	11/20/24 14:47	PB165124

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units
TARGETS						
12674-11-2	Aroclor-1016	11.8	U	11.8	59.0	ug/kg
11104-28-2	Aroclor-1221	22.2	U	22.2	59.0	ug/kg
11141-16-5	Aroclor-1232	11.8	U	11.8	59.0	ug/kg
53469-21-9	Aroclor-1242	11.8	U	11.8	59.0	ug/kg
12672-29-6	Aroclor-1248	27.4	U	27.4	59.0	ug/kg
11097-69-1	Aroclor-1254	358		9.50	59.0	ug/kg
37324-23-5	Aroclor-1262	15.8	U	15.8	59.0	ug/kg
11100-14-4	Aroclor-1268	11.9	U	11.9	59.0	ug/kg
11096-82-5	Aroclor-1260	10.1	U	10.1	59.0	ug/kg
Total PCBs	Total PCBs	358		9.50	59.0	ug/kg
SURROGATES						
877-09-8	Tetrachloro-m-xylene	18.9		32 - 144	95%	SPK: 20
2051-24-3	Decachlorobiphenyl	21.1		32 - 175	105%	SPK: 20

Comments:

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 E = Value Exceeds Calibration Range
 P = Indicates >25% difference for detected concentrations between the two GC columns
 Q = indicates LCS control criteria did not meet requirements
 M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 N = Presumptive Evidence of a Compound
 * = Values outside of QC limits
 D = Dilution
 S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.
 () = Laboratory InHouse Limit

Report of Analysis

Client:	ATC Group Services LLC		Date Collected:	11/14/24	
Project:	P.S. 220 - QUEEN		Date Received:	11/19/24	
Client Sample ID:	ROOM-126		SDG No.:	P4918	
Lab Sample ID:	P4918-05		Matrix:	CAULK	
Analytical Method:	SW8082A		% Solid:	100	Decanted:
Sample Wt/Vol:	1.02	Units: g	Final Vol:	10000	uL
Soil Aliquot Vol:		uL	Test:	PCB Group1	
Extraction Type:			Injection Volume :		
GPC Factor :	1.0	PH :			
Prep Method :	SW3541B				

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
PP068628.D	1	11/20/24 08:22	11/20/24 15:04	PB165124

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units
TARGETS						
12674-11-2	Aroclor-1016	99.7	U	99.7	500	ug/kg
11104-28-2	Aroclor-1221	189	U	189	500	ug/kg
11141-16-5	Aroclor-1232	100	U	100	500	ug/kg
53469-21-9	Aroclor-1242	99.7	U	99.7	500	ug/kg
12672-29-6	Aroclor-1248	232	U	232	500	ug/kg
11097-69-1	Aroclor-1254	358	J	80.3	500	ug/kg
37324-23-5	Aroclor-1262	134	U	134	500	ug/kg
11100-14-4	Aroclor-1268	101	U	101	500	ug/kg
11096-82-5	Aroclor-1260	85.6	U	85.6	500	ug/kg
Total PCBs	Total PCBs	358	J	80.3	500	ug/kg
SURROGATES						
877-09-8	Tetrachloro-m-xylene	21.0		32 - 144	105%	SPK: 20
2051-24-3	Decachlorobiphenyl	22.5		32 - 175	112%	SPK: 20

Comments:

U = Not Detected	J = Estimated Value
LOQ = Limit of Quantitation	B = Analyte Found in Associated Method Blank
MDL = Method Detection Limit	N = Presumptive Evidence of a Compound
LOD = Limit of Detection	* = Values outside of QC limits
E = Value Exceeds Calibration Range	D = Dilution
P = Indicates >25% difference for detected concentrations between the two GC columns	S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.
Q = indicates LCS control criteria did not meet requirements	() = Laboratory InHouse Limit
M = MS/MSD acceptance criteria did not meet requirements	

LAB CHRONICLE

OrderID: P4918	OrderDate: 11/19/2024 10:35:10 AM
Client: ATC Group Services LLC	Project: P.S. 220 - QUEEN
Contact: Olga Seldinas	Location: L51

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
P4918-01	ROOF-1-CHIMNEY-GR EY	CAULK			11/19/24			11/19/24
			PCB Group1	8082A		11/20/24	11/20/24	
P4918-02	ROOF-1-2A-2B-2C	CAULK			11/19/24			11/19/24
			PCB Group1	8082A		11/20/24	11/20/24	
P4918-03	ROOF-2-3A-3B-3C	CAULK			11/19/24			11/19/24
			PCB Group1	8082A		11/20/24	11/20/24	
P4918-04	EXTERIOR-EXIT-2	CAULK			11/19/24			11/19/24
			PCB Group1	8082A		11/20/24	11/20/24	
P4918-05	ROOM-126	CAULK			11/14/24			11/19/24
			PCB Group1	8082A		11/20/24	11/20/24	



SHIPPING DOCUMENTS

CLIENT INFORMATION	PROJECT INFORMATION
COMPANY: ATC Group Services	PROJECT NAME: PS. 220-Queen
ADDRESS: 104 East 25th Street	PROJECT #: 2022.SCA399 LOCATION: Queen
CITY: New York STATE: NY ZIP: 10010	PROJECT MANAGER: Oiga Seldin
ATTENTION: Oiga Seldin	E-MAIL: oiga.seldin@oneatn.com
PHONE: 212 284 0619 FAX:	PHONE: 212 284-0619

BILLING INFORMATION	
BILL TO:	PO#
ADDRESS:	
CITY:	STATE: ZIP:
ATTENTION:	PHONE:

DATA TURNAROUND INFORMATION
FAX: 5 days. DAYS*
HARD COPY: DAYS*
EDD DAYS*
* TO BE APPROVED BY CHEMTECH STANDARD TURNAROUND TIME IS 10 BUSINESS DAYS

DATA DELIVERABLE INFORMATION
<input type="checkbox"/> RESULTS ONLY (L1) <input type="checkbox"/> US EPA CLP (L4) <input type="checkbox"/> RESULTS + QC (L2) <input type="checkbox"/> NYS ASP "A" (L2) <input type="checkbox"/> NJ REDUCED (L3) <input type="checkbox"/> NYS ASP "B" (L4) <input type="checkbox"/> NJ FULL (L4) <input type="checkbox"/> Other _____ <input type="checkbox"/> EDD Format

ANALYSIS								
TOTAL PCB								
1	2	3	4	5	6	7	8	9

PRESERVATIVES									COMMENTS
									<- Specify Preservatives A-HCl B-HNO3 C-H2SO4 D-NaOH E-ICE F-Other
1	2	3	4	5	6	7	8	9	

CHEMTECH SAMPLE ID	PROJECT SAMPLE IDENTIFICATION	SAMPLE MATRIX	SAMPLE TYPE		SAMPLE COLLECTION		# of Bottles											
			COMP	GRAB	DATE	TIME		1	2	3	4	5	6	7	8	9		
1.	Roof #1 - Chimney base	caulk	✓		11/14/24	5 PM												
2.	Roof #1 - EA 2020 grey caulk to patch patch	caulk	✓		11/14/24	3:20 PM												
3.	Roof #2: 3A 3B 3C grey caulk on chimney base	caulk	✓		11/14/24	5:40 PM												
4.	Roof #2: exterior concrete pavement	caulk	✓		11/14/24	4 PM												
5.	Room 12-B grey interior caulk	caulk	✓		11/14/24	4:20 PM												
6.																		
7.																		
8.																		
9.																		
10.																		

SAMPLE CUSTODY MUST BE DOCUMENTED BELOW EACH TIME SAMPLES CHANGE POSSESSION INCLUDING COURIER DELIVERY			
RELINQUISHED BY SAMPLER	DATE/TIME	RECEIVED BY	Conditions of bottles or coolers at receipt: <input type="checkbox"/> Compliant <input type="checkbox"/> Non Compliant <input type="checkbox"/> Cooler Temp 20.6
1. Oiga Seldin	11/18/2024		<input type="checkbox"/> MeOH extraction requires an additional 4oz. Jar for percent solid
RELINQUISHED BY	DATE/TIME	RECEIVED BY	Comments:
2. [Signature]	9:57	[Signature]	
RELINQUISHED BY	DATE/TIME	RECEIVED FOR LAB BY	SHIPPED VIA: CLIENT: <input type="checkbox"/> Hand Delivered <input type="checkbox"/> Overnight <input type="checkbox"/> Picked Up <input type="checkbox"/> Overnight
3. [Signature]	11-19-24		<input type="checkbox"/> Shipment Complete <input type="checkbox"/> YES <input type="checkbox"/> NO

Laboratory Composite Sample log

Chemtech Project number: P4918

Date: 11-19-24

Client Name: A.T.C

Client Project Name: P.S. 220 - QUEEN

Instructions: Composite Samples (3:1)

Sample Custodian: C. Peña

Client Sample ID	Weigh / Volume used	New ID	Sample Description	Sample Composite time	Comments
Roof-1-Chimney Grey	0.53g	Roof-1-Chimney-Grey	Grey Caulk	11:20	Total weight (1.62g)
↓	0.55g	↓	↓	↓	↓
↓	0.54g	↓	↓	↓	↓
Roof-1-2A.	3.25g	Roof-1-2A-2B-2C	Grey Caulk	11:23	Total weight (9.70g)
2B	3.22g	↓	↓	↓	↓
2C	3.23g	↓	↓	↓	↓
Roof-2-3A Exterior-Exit-2 CP	3.38g	Roof-2-3A-3B-3C	Dark Caulk	11:26	Total weight (10.19g)
↓ 3B	3.40g	↓	↓	↓	↓
↓ 3C	3.41g	↓	↓	↓	↓
Exterior-Exit-2 Room 126 CP	3.47g	Exterior-Exit-2	DARK CAULK	11:32	Total weight (10.43g)
↓	3.51g	↓	↓	↓	↓

Laboratory Certification

Certified By	License No.
CAS EPA CLP Contract	68HERH20D0011
Connecticut	PH-0830
DOD ELAP (ANAB)	L2219
Maine	2024021
Maryland	296
New Hampshire	255424 Rev 1
New Jersey	20012
New York	11376
Pennsylvania	68-00548
Soil Permit	525-24-234-08441
Texas	T104704488