

Report of Analysis

Client:	Parkway Generation Operating LLC	Date Collected:	11/21/24 12:00
Project:	2024 Blanket PO #LIND7460 - Unit Price List	Date Received:	11/21/24
Client Sample ID:	BW-2	SDG No.:	P4946
Lab Sample ID:	P4946-02	Matrix:	SOIL
		% Solid:	99.5

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.53	H	1	0	0	pH		11/22/24 13:35	9045D
Ignitability	NO		1	0	0	oC		11/22/24 12:40	1030
Reactive Cyanide	0.0087	U	1	0.0087	0.050	mg/Kg	11/25/24 09:00	11/25/24 12:43	9012B
Reactive Sulfide	6.31	J	1	0.19	10.0	mg/Kg	11/25/24 13:50	11/26/24 08:23	9034

Comments: pH result reported at temperature 23.6 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits