

Duplicate Sample Summary

Client:	Tully Environmental, Inc	SDG No.:	P4967
Project:	Transfer Station-SPDES	Sample ID:	P4967-01
Client ID:	001-WILLETS-PT-BLVDDUP	Percent Solids for Spike Sample:	0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
TSS	mg/L	+/-5	38.8		40.0		1	3.05		11/25/2024