

Report of Analysis

Client:	Weston Solutions	Date Collected:	11/22/24
Project:	Ft Meade Tipton Airfield Parcel RI - PO 0111169	Date Received:	11/23/24
Client Sample ID:	TAPIAL1-SB04D-9-112224-00-T1	SDG No.:	P4986
Lab Sample ID:	P4986-01	Matrix:	SOIL
Level (low/med):	low	% Solid:	93.9

Cas	Parameter	Conc.	Qua.	DF	MDL	LOD	LOQ / CRQL	Units(Dry Weight)	Prep Date	Date Ana.	Ana Met.	Prep Met.
7439-97-6	Mercury	0.010	U	1	0.0060	0.010	0.013	mg/Kg	11/27/24 08:15	11/27/24 12:57	SW7471B	

Color Before:

Clarity Before:

Texture:

Color After:

Clarity After:

Artifacts:

Comments: METALS-TAL

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits