

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: New York City DEP of Environmental Protection/BWS Date Collected: 11/25/24 09:54

Project: Industrial Wastewater Discharge Permit - Fall 2024 Date Received: 11/25/24

Client Sample ID: 14B-3 SDG No.: P4997

Lab Sample ID: P4997-03 Matrix: WATER

% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Field pH	6.73		1	0	0	pН		11/25/24 09:57	SM4500-H B
Field Temperature	13.3		1	0	0	o C		11/25/24 09:57	SM 2550 B-10
Non-Polar Material	0.60	J	1	0.40	5.00	mg/L		12/02/24 09:40	1664A
TSS	4720		1	1.00	4.00	mg/L		11/26/24 10:00	SM 2540 D-15

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits