

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 11/25/24 10:03 Project: Bergen Point 69kV - 4KV-13KV Conversion Project OP Date Received: 11/25/24 Client Sample ID: MH-745 SDG No.: P5000 Lab Sample ID: P5000-01 Matrix: **SOIL** % Solid: 82.7

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weigh	ıt) Prep Date	Date Ana.	Ana Met.
Hexavalent Chromium	0.48	U	1	0.095	0.48	mg/Kg	11/26/24 13:00	11/26/24 16:01	7196A
Ignitability	NO		1	0	0	oC		11/26/24 11:23	1030
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		11/26/24 09:40	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits