

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Date Collected: 11/25/24 15:30

Project: 540 Degraw St, Brooklyn, NY - E9309 Date Received: 11/26/24

Client Sample ID: TW-WTS-02DL SDG No.: P5006

Lab Sample ID: P5006-18DL Matrix: WATER

% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Chloride	231	OR	2	0.022	1.20	mg/L		11/26/24 16:07	300.0
Nitrate	9.40	D	2	0.0068	1.00	mg/L		11/26/24 16:07	300.0

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits