

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: New York City DEP of Environmental Protection/BWS Date Collected: 11/26/24 07:00

Project: Industrial Wastewater Discharge Permit - Fall 2024 Date Received: 11/26/24

Client Sample ID: 14B-1 SDG No.: P5018

Lab Sample ID: P5018-01 Matrix: WATER

% Solid: 0

| Parameter | Conc. | Qua. | DF | MDL | LOQ / CRQL | Units | Prep Date | Date Ana. | Ana Met. |
|--------------------|-------|------|----|------|------------|-------|-----------|----------------|--------------|
| Field pH | 6.76 | | 1 | 0 | 0 | pН | | 11/26/24 07:03 | SM4500-H B |
| Field Temperature | 13.3 | | 1 | 0 | 0 | o C | | 11/26/24 07:03 | SM 2550 B-10 |
| Non-Polar Material | 0.60 | J | 1 | 0.40 | 5.00 | mg/L | | 12/02/24 09:40 | 1664A |
| TSS | 3540 | | 1 | 1.00 | 4.00 | mg/L | | 11/27/24 08:30 | SM 2540 D-15 |

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits