

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: New York City DEP of Environmental Protection/BWS Date Collected: 11/26/24 07:59

Project: Industrial Wastewater Discharge Permit - Fall 2024 Date Received: 11/26/24

Client Sample ID: 14B-2 SDG No.: P5018

Lab Sample ID: P5018-02 Matrix: WATER

% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Field pH	6.80		1	0	0	pН		11/26/24 08:02	SM4500-H B
Field Temperature	13.1		1	0	0	o C		11/26/24 08:02	SM 2550 B-10
Non-Polar Material	0.70	J	1	0.40	5.00	mg/L		12/02/24 09:40	1664A
TSS	3480		1	1.00	4.00	mg/L		11/27/24 08:30	SM 2540 D-15

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits