

LAB CHRONICLE

OrderID:	P5026	OrderDate:	11/27/2024 11:24:00 AM
Client:	Tully Construction Co., Inc.	Project:	Hamilton
Contact:	Dean Devoe	Location:	L61,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
P5026-02	SOIL-1-HAM	SOIL			11/27/24 10:42			11/27/24
			Corrosivity	9045D			11/27/24 15:27	
			Ignitability	1030			12/03/24 12:37	
			Reactive Cyanide	9012B		12/02/24	12/02/24 12:28	
			Reactive Sulfide	9034		12/02/24	12/02/24 15:09	
P5026-06	SOIL-2-HAM	SOIL			11/27/24 11:10			11/27/24
			Corrosivity	9045D			11/27/24 15:35	
			Ignitability	1030			12/03/24 12:45	
			Reactive Cyanide	9012B		12/02/24	12/02/24 12:28	
			Reactive Sulfide	9034		12/02/24	12/02/24 15:12	