

Matrix Spike/Matrix Spike Duplicate Summary

SW-846

SDG No.: P5026

Client: Tully Construction Co., Inc.

Analytical Method: 8082A

DataFile : PO108286.D

Lab Sample ID:	Parameter	Spike	Sample Result	Result	Units	Rec	Rec Qual	RPD	RPD Qual	Low	Limits High	RPD
Client Sample ID:	SOIL-1-HAMMS											
P5026-05MS	AR1016	214.2	0	200	ug/kg	93				55	146	
	AR1260	214.2	0	165	ug/kg	77				45	144	