

Matrix Spike/Matrix Spike Duplicate Summary

SW-846

SDG No.: P5026

Client: Tully Construction Co., Inc.

Analytical Method: 8082A

DataFile : PO108287.D

Lab Sample ID:	Parameter	Spike	Sample		Units	Rec	Rec		RPD		Limits	
			Result	Result			Qual	RPD	Qual	Low	High	RPD
Client Sample ID: P5026-05MSD	SOIL-1-HAMMSD											
	AR1016	213.8	0	199	ug/kg	93		0		55	146	20
	AR1260	213.8	0	168	ug/kg	79		3		45	144	20