

Surrogate Summary

SW-846

SDG No.: P5026

Client: Tully Construction Co., Inc.

Analytical Method: 8270E

Lab Sample ID	Client ID	Parameter	Spike (PPM)	Result (PPM)	Recovery (%)	Qual	Limits (%)	
							Low	High
P5026-01	SOIL-1-HAM	Nitrobenzene-d5	100	63.6	64		18	107
		2-Fluorobiphenyl	100	62.2	62		20	109
		Terphenyl-d14	100	53.1	53		10	105
P5026-05		Nitrobenzene-d5	100	56.2	56		18	107
		2-Fluorobiphenyl	100	55.9	56		20	109
		Terphenyl-d14	100	52.2	52		10	105
P5026-05MS	SOIL-1-HAMMS	Nitrobenzene-d5	100	51.3	51		18	107
		2-Fluorobiphenyl	100	49.7	50		20	109
		Terphenyl-d14	100	47.1	47		10	105
P5026-05MSD	SOIL-1-HAMMSD	Nitrobenzene-d5	100	57.7	58		18	107
		2-Fluorobiphenyl	100	56.4	56		20	109
		Terphenyl-d14	100	51.2	51		10	105
PB165312BL	PB165312BL	Nitrobenzene-d5	100	86.6	87		18	107
		2-Fluorobiphenyl	100	90.4	90		20	109
		Terphenyl-d14	100	91.0	91		10	105
PB165312BS	PB165312BS	Nitrobenzene-d5	100	84.7	85		18	107
		2-Fluorobiphenyl	100	88.5	88		20	109
		Terphenyl-d14	100	95.2	95		10	105