

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 12/03/24 15:35 Project: Bergen Point 69kV - 4KV-13KV Conversion Project OP Date Received: 12/03/24 Client Sample ID: MH-737 SDG No.: P5072 Lab Sample ID: P5072-01 Matrix: SOIL % Solid: 91.7

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weigh	nt) Prep Date	Date Ana.	Ana Met.
Hexavalent Chromium	0.43	U	1	0.085	0.43	mg/Kg	12/04/24 14:10	12/05/24 09:26	7196A
Ignitability	NO		1	0	0	oC		12/04/24 09:02	1030
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		12/05/24 11:05	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits