

Report of Analysis

Client:	Weston Solutions	Date Collected:	12/02/24 15:00
Project:	Ft Meade Tipton Airfield Parcel RI - PO 0111169	Date Received:	12/04/24
Client Sample ID:	TAPIAL2-SB02I-7.5-120224-00-T1	SDG No.:	P5076
Lab Sample ID:	P5076-01	Matrix:	SOIL
		% Solid:	93.9

Parameter	Conc.	Qua.	DF	MDL	LOD	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
pH	5.27	H	1	0	0	0	pH		12/05/24 10:10	9045D
TOC	1140		1	19.8	50.0	250	mg/Kg		12/06/24 15:17	9060A

Comments: pH result reported at temperature 20.6 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits