

Report of Analysis

Client:	R3M Engineering, Inc.	Date Collected:	12/04/24 11:00
Project:	MC054.36 23-8-1 LM - Landing Lane New Brunswick	Date Received:	12/04/24
Client Sample ID:	LL-001-FB-12-4-24	SDG No.:	P5093
Lab Sample ID:	P5093-02	Matrix:	WATER
		% Solid:	0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.00099	U	1	0.00099	0.0050	mg/L	12/07/24 10:00	12/09/24 12:47	9012B
TOC	0.82	J	1	0.19	1.00	mg/L		12/05/24 14:29	9060A

Comments: _____

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N = Spiked sample recovery not within control limits