

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

mg/Kg

12/04/24 13:50

12/04/24 16:30

9034

Fax: 908 789 8922

0.19

Report of Analysis

Client: **PSEG** Date Collected: 12/04/24 23:15

Project: PSEG S Elmora Ave WC Date Received: 12/04/24

Client Sample ID: SDG No.: P5096 MH-B

Lab Sample ID: P5096-04 Matrix: SOIL % Solid: 100

Parameter DF MDL LOQ / CRQL Units **Prep Date** Ana Met. Conc. Qua. Date Ana. Corrosivity 8.57 рΗ 12/05/24 09:05 9045D Ignitability NO 1 0 0 oC12/05/24 10:12 1030 Reactive Cyanide 0.050 U 1 0.00880.050 mg/Kg 9012B 12/05/24 11:00 12/05/24 14:36 Reactive Sulfide 4.77 J

10.0

Comments: pH result reported at temperature 20.4 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits