

Matrix Spike/Matrix Spike Duplicate Summary

SW-846

SDG No.: P5112

Client: Tully Construction Co., Inc.

Analytical Method: 8082A

DataFile : PP068845.D

Lab Sample ID:	Parameter	Spike	Sample		Units	Rec	Rec		RPD		Limits	
			Result	Result			Qual	RPD	Qual	Low	High	RPD
Client Sample ID:	TAPIAL2-IDW-SOIL-120424-00-T2MS											
P5117-02MS	AR1016	208.4	0	226	ug/kg	108				55		146
	AR1260	208.4	0	207	ug/kg	99				45		144