

Surrogate Summary

SW-846

SDG No.: P5112

Client: Tully Construction Co., Inc.

Analytical Method: 8270E

Lab Sample ID	Client ID	Parameter	Spike (PPM)	Result (PPM)	Recovery (%)	Qual	Limits (%)	
							Low	High
P5112-01	10TH-ST-SOIL	Nitrobenzene-d5	100	97.0	97		18	107
		2-Fluorobiphenyl	100	104	104		20	109
		Terphenyl-d14	100	78.3	78		10	105
P5112-01DL	10TH-ST-SOILDL	Nitrobenzene-d5	100	94.4	94		18	107
		2-Fluorobiphenyl	100	108	108		20	109
		Terphenyl-d14	100	81.9	82		10	105
P5112-01MS	10TH-ST-SOILMS	Nitrobenzene-d5	100	79.0	79		18	107
		2-Fluorobiphenyl	100	84.0	84		20	109
		Terphenyl-d14	100	67.0	67		10	105
P5112-01MSD	10TH-ST-SOILMSD	Nitrobenzene-d5	100	80.2	80		18	107
		2-Fluorobiphenyl	100	85.6	86		20	109
		Terphenyl-d14	100	66.1	66		10	105
PB165423BL	PB165423BL	Nitrobenzene-d5	100	92.7	93		18	107
		2-Fluorobiphenyl	100	97.3	97		20	109
		Terphenyl-d14	100	82.4	82		10	105
PB165423BS	PB165423BS	Nitrobenzene-d5	100	92.3	92		18	107
		2-Fluorobiphenyl	100	95.9	96		20	109
		Terphenyl-d14	100	96.0	96		10	105