

Surrogate Summary

SDG No.: P5112

Client: Tully Construction Co., Inc.

Analytical Method: SW8260D

Lab Sample ID	Client ID	Parameter	Spike	Result	RecoveryQual	Limits	
						Low	High
P5112-01	10TH-ST-SOIL	1,2-Dichloroethane-d4	50	51.6	103	50	163
		Dibromofluoromethane	50	49.7	99	54	147
		Toluene-d8	50	49.9	100	58	134
		4-Bromofluorobenzene	50	33.5	67	29	146
VY1206SBL01	VY1206SBL01	1,2-Dichloroethane-d4	50	52.3	105	50	163
		Dibromofluoromethane	50	49.2	98	54	147
		Toluene-d8	50	50.5	101	58	134
		4-Bromofluorobenzene	50	41.7	83	29	146
VY1206SBS01	VY1206SBS01	1,2-Dichloroethane-d4	50	54.0	108	50	163
		Dibromofluoromethane	50	52.7	105	54	147
		Toluene-d8	50	51.9	104	58	134
		4-Bromofluorobenzene	50	53.5	107	29	146
VY1206SBSD01	VY1206SBSD01	1,2-Dichloroethane-d4	50	58.3	117	50	163
		Dibromofluoromethane	50	54.2	108	54	147
		Toluene-d8	50	52.7	105	58	134
		4-Bromofluorobenzene	50	54.4	109	29	146