

Report of Analysis

Client:	Weston Solutions	Date Collected:	12/04/24 13:00
Project:	Ft Meade Tipton Airfield Parcel RI - PO 0111169	Date Received:	12/05/24
Client Sample ID:	TAPIAL2-IDW-SOIL-120424-00-T2	SDG No.:	P5117
Lab Sample ID:	P5117-02	Matrix:	SOIL
		% Solid:	79.8

Parameter	Conc.	Qua.	DF	MDL	LOD	LOQ / CRQL	Units(Dry Weight)	Prep Date	Date Ana.	Ana Met.
Cyanide	0.25	U	1	0.055	0.25	0.31	mg/Kg	12/07/24 10:00	12/09/24 12:54	9012B
Ignitability	NO		1	0	0	0	oC		12/07/24 08:30	1030
pH	6.41	H	1	0	0	0	pH		12/06/24 09:35	9045D
Sulfide	4.00	J	1	2.33	6.25	12.5	mg/Kg	12/11/24 10:10	12/11/24 14:41	9034

Comments: pH result reported at temperature 20.1 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits