



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Hit Summary Sheet
SW-846

SDG No.: P5117

Order ID: P5117

Client: Weston Solutions

Project ID: Ft Meade Tipton Airfield Parcel RI - PO 01

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	LOD	RDL	Units
Client ID : TAPIAL2-IDW-SOIL-120424-00-T2									
P5117-02	TAPIAL2-IDW-SOIL-120424-00	TCLP	Barium	841		62.8	125	500	ug/L
P5117-02	TAPIAL2-IDW-SOIL-120424-00	TCLP	Chromium	23.2	J	6.60	25.0	50.0	ug/L



SAMPLE DATA

A

B

C

D

Report of Analysis

Client:	Weston Solutions	Date Collected:	12/04/24
Project:	Ft Meade Tipton Airfield Parcel RI - PO 0111169	Date Received:	12/05/24
Client Sample ID:	TAPIAL2-IDW-SOIL-120424-00-T2	SDG No.:	P5117
Lab Sample ID:	P5117-02	Matrix:	TCLP
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOD	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-38-2	Arsenic	80.0	U	1	34.8	80.0	100	ug/L	12/06/24 11:10	12/09/24 14:14	SW6010	SW3050
7440-39-3	Barium	841	N	1	62.8	125	500	ug/L	12/06/24 11:10	12/09/24 14:14	SW6010	SW3050
7440-43-9	Cadmium	7.50	U	1	0.94	7.50	30.0	ug/L	12/06/24 11:10	12/09/24 14:14	SW6010	SW3050
7440-47-3	Chromium	23.2	J	1	6.60	25.0	50.0	ug/L	12/06/24 11:10	12/09/24 14:14	SW6010	SW3050
7439-92-1	Lead	48.0	U	1	35.1	48.0	60.0	ug/L	12/06/24 11:10	12/09/24 14:14	SW6010	SW3050
7439-97-6	Mercury	1.60	U	1	0.81	1.60	2.00	ug/L	12/09/24 08:55	12/09/24 12:37	SW7470A	
7782-49-2	Selenium	80.0	U	1	58.8	80.0	100	ug/L	12/06/24 11:10	12/09/24 14:14	SW6010	SW3050
7440-22-4	Silver	25.0	U	1	5.80	25.0	50.0	ug/L	12/06/24 11:10	12/09/24 14:14	SW6010	SW3050

Color Before:	Colorless	Clarity Before:	Clear	Texture:
Color After:	Colorless	Clarity After:	Clear	Artifacts:
Comments:	TCLP METALS			

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N = Spiked sample recovery not within control limits

LAB CHRONICLE

OrderID:	P5117	OrderDate:	12/5/2024 10:55:00 AM
Client:	Weston Solutions	Project:	Ft Meade Tipton Airfield Parcel RI - PO 0111169
Contact:	Nathan Fretz	Location:	L41

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
P5117-01	TAPIAL3-SB04I-10-12 0324-00-T1	SOIL			12/03/24			12/05/24
			Mercury	7471B		12/06/24	12/06/24	
			Metals ICP-TAL	6020B		12/18/24	12/19/24	
P5117-02	TAPIAL2-IDW-SOIL-1 20424-00-T2	TCLP			12/04/24			12/05/24
			TCLP ICP Metals	6010D		12/06/24	12/09/24	
			TCLP Mercury	7470A		12/09/24	12/09/24	