



A

B

C

# SAMPLE DATA

## Report of Analysis

Client:	Weston Solutions	Date Collected:	12/04/24 13:00
Project:	Ft Meade Tipton Airfield Parcel RI - PO 0111169	Date Received:	12/05/24
Client Sample ID:	TAPIAL2-IDW-SOIL-120424-00-T2	SDG No.:	P5120
Lab Sample ID:	P5120-01	Matrix:	SOIL
		% Solid:	79.8

Parameter	Conc.	Qua.	DF	MDL	LOD	LOQ / CRQL	Units(Dry Weight)	Prep Date	Date Ana.	Ana Met.
Reactive Cyanide	0.025	U	1	0.0088	0.025	0.050	mg/Kg	12/05/24 11:00	12/05/24 14:43	9012B
Reactive Sulfide	3.19	J	1	0.19	5.00	10.0	mg/Kg	12/06/24 08:50	12/06/24 12:48	9034

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits

LAB CHRONICLE

OrderID:	P5120	OrderDate:	12/5/2024 10:59:00 AM
Client:	Weston Solutions	Project:	Ft Meade Tipton Airfield Parcel RI - PO 0111169
Contact:	Nathan Fretz	Location:	L51

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
P5120-01	TAPIAL2-IDW-SOIL-1 20424-00-T2	SOIL			12/04/24 13:00			12/05/24
			Reactive Cyanide	9012B		12/05/24	12/05/24 14:43	
			Reactive Sulfide	9034		12/06/24	12/06/24 12:48	