

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

- COVER PAGE -INORGANIC ANALYSIS DATA PACKAGE

Client:	Tully Environmental, Inc				
SDG No.:	P5138				
Contract:	TULL01	L	ab Code: CHEM	Case No.: P5	138 SAS No.: P5138
	Lab Sample ID	<u>C</u>	Client Sample II)	QC Description
	P5138-01	_	01-WILLETS-PT-B		•
	P5138-02	00	02-35TH-AVE(NO	V)	
	P5138-02DUP	00	02-35TH-AVE(NO	V)DUP	Sample Duplicate
	P5138-02MS	00	02-35TH-AVE(NO	V)MS	Matrix Spike
	P5138-02MSD	00	02-35TH-AVE(NO	V)MSD	Matrix Spike Duplicate
Were ICP inter	relement corrections applied?	Yes/No			
Were ICP background corrections applied?		Yes/No			
	w data generated before				
applications of background corrections?		Yes/No			
Comments:					
	-				
	is data package is in compliance technically and for completeness				
	e of the data contained in this has			eadable data submitted	on diskette has been
authorized by	the Laboratory Manager or the M	fanager's designee, as v	verified by the follow	ving signature.	
Signature:			Name:	JSathvara	
		<u></u>			
Date:		Title:	ANALYST		