

## Report of Analysis

Client:	VERINA CONSULTING GROUP, LLC	Date Collected:	12/05/24 10:43
Project:	Rotor Clip - PO# 5183.0001	Date Received:	12/05/24
Client Sample ID:	WATER TREATMENT DISCHARGE	SDG No.:	P5141
Lab Sample ID:	P5141-02	Matrix:	WATER
		% Solid:	0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.0024	J	1	0.00099	0.0050	mg/L	12/07/24 10:00	12/09/24 12:54	9012B
Oil and Grease	1.10	J	1	0.40	5.00	mg/L		12/06/24 10:30	1664A

Comments: \_\_\_\_\_

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits