

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: Parkway Generation Operating LLC Date Collected: 12/05/24 09:50

Project: Linden Generating Station - LRSA Date Received: 12/05/24

Client Sample ID: DSN001 SDG No.: P5143

Lab Sample ID: P5143-03 Matrix: WATER

% Solid: 0

Parameter	Conc. Qu	ua. D	F MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
BOD5	2.00 U	U 1	0.17	2.00	mg/L		12/05/24 17:40	SM 5210 B-16
COD	94.6	1	2.35	10.0	mg/L		12/09/24 14:24	SM 5220 D-11
TSS	16.1	1	1.00	4.00	mg/L		12/09/24 11:00	SM 2540 D-15

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits