

 $284 \; Sheffield \; Street, \; Mountainside, \; New \; Jersey \; 07092, \; Phone \; : \; 908 \; 789 \; 8900, \\$

Fax: 908 789 8922

Report of Analysis

Client: Holland Manufacturing Co. Date Collected: 12/05/24 10:45 Project: Pre Treatment Plant Date Received: 12/05/24 Client Sample ID: **AERATION TK 1** SDG No.: P5146 Lab Sample ID: P5146-04 Matrix: WATER % Solid:

Parameter	Conc. Qua	a. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
TSS	2690	1 1.00	4.00	mg/L		12/09/24 11:0	00 SM 2540 D-15

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits