

Report of Analysis

| | | | |
|-------------------|---|-----------------|----------------|
| Client: | Weston Solutions | Date Collected: | 12/06/24 11:40 |
| Project: | Ft Meade Tipton Airfield Parcel RI - PO 0111169 | Date Received: | 12/07/24 |
| Client Sample ID: | TAPIAL3-SB03I-15-120624-00-T1 | SDG No.: | P5213 |
| Lab Sample ID: | P5213-01 | Matrix: | SOIL |
| | | % Solid: | 89.6 |

| Parameter | Conc. | Qua. | DF | MDL | LOD | LOQ / CRQL | Units | Prep Date | Date Ana. | Ana Met. |
|-----------|-------|------|----|------|------|------------|-------|-----------|----------------|----------|
| pH | 5.00 | H | 1 | 0 | 0 | 0 | pH | | 12/10/24 08:15 | 9045D |
| TOC | 753 | | 1 | 19.8 | 50.0 | 250 | mg/Kg | | 12/17/24 12:42 | 9060A |

Comments: pH result reported at temperature 23.1 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits