

LAB CHRONICLE

OrderID:	P5279	OrderDate:	12/13/2024 12:03:00 PM
Client:	Tully Construction Co., Inc.	Project:	MTA Rockaway Park
Contact:	Dean Devoe	Location:	L51,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
P5279-02	ROCKAWAY-PARK	SOIL			12/13/24 08:20			12/13/24
			Corrosivity	9045D			12/18/24 08:40	
			Ignitability	1030			12/19/24 13:10	
			Reactive Cyanide	9012B		12/19/24	12/19/24 12:10	
			Reactive Sulfide	9034		12/17/24	12/17/24 11:13	