



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Initial and Continuing Calibration Verification

Client: Tully Construction Co., Inc.

SDG No.: P5279

Project: MTA Rockaway Park

RunNo.: LB133987

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: Corrosivity	ICV	pH	7.00	7	100	90-110	12/18/2024
Sample ID: Corrosivity	CCV1	pH	2.02	2.00	101	90-110	12/18/2024
Sample ID: Corrosivity	CCV2	pH	12.02	12.00	100	90-110	12/18/2024

Initial and Continuing Calibration Verification

Client: Tully Construction Co., Inc.

SDG No.: P5279

Project: MTA Rockaway Park

RunNo.: LB134015

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Reactive Cyanide	mg/L	0.098	0.099	99	85-115	12/19/2024
Sample ID: CCV1 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	12/19/2024
Sample ID: CCV2 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	12/19/2024
Sample ID: CCV3 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	12/19/2024