



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Hit Summary Sheet
SW-846

SDG No.: P5279

Order ID: P5279

Client: Tully Construction Co., Inc.

Project ID: MTA Rockaway Park

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	RDL	Units
Client ID : ROCKAWAY-PARK								
P5279-02	ROCKAWAY-PARK	TCLP	Barium	629		62.8	500	ug/L
P5279-02	ROCKAWAY-PARK	TCLP	Cadmium	1.07	J	0.94	30.0	ug/L
P5279-02	ROCKAWAY-PARK	TCLP	Chromium	8.27	J	6.60	50.0	ug/L
P5279-02	ROCKAWAY-PARK	TCLP	Lead	37.6	J	35.1	60.0	ug/L



SAMPLE DATA

A

B

C

D

Report of Analysis

Client:	Tully Construction Co., Inc.	Date Collected:	12/13/24
Project:	MTA Rockaway Park	Date Received:	12/13/24
Client Sample ID:	ROCKAWAY-PARK	SDG No.:	P5279
Lab Sample ID:	P5279-02	Matrix:	TCLP
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-38-2	Arsenic	34.8	U	1	34.8	100	ug/L	12/18/24 12:00	12/20/24 17:16	SW6010	SW3050
7440-39-3	Barium	629		1	62.8	500	ug/L	12/18/24 12:00	12/20/24 17:16	SW6010	SW3050
7440-43-9	Cadmium	1.07	J	1	0.94	30.0	ug/L	12/18/24 12:00	12/20/24 17:16	SW6010	SW3050
7440-47-3	Chromium	8.27	J	1	6.60	50.0	ug/L	12/18/24 12:00	12/20/24 17:16	SW6010	SW3050
7439-92-1	Lead	37.6	J	1	35.1	60.0	ug/L	12/18/24 12:00	12/20/24 17:16	SW6010	SW3050
7439-97-6	Mercury	0.81	UN	1	0.81	2.00	ug/L	12/19/24 07:58	12/19/24 12:41	SW7470A	
7782-49-2	Selenium	58.8	U	1	58.8	100	ug/L	12/18/24 12:00	12/20/24 17:16	SW6010	SW3050
7440-22-4	Silver	5.80	UN	1	5.80	50.0	ug/L	12/18/24 12:00	12/20/24 17:16	SW6010	SW3050

Color Before:	Colorless	Clarity Before:	Clear	Texture:
Color After:	Colorless	Clarity After:	Clear	Artifacts:
Comments:	TCLP METALS			

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N =Spiked sample recovery not within control limits

LAB CHRONICLE

OrderID:	P5279	OrderDate:	12/13/2024 12:03:00 PM
Client:	Tully Construction Co., Inc.	Project:	MTA Rockaway Park
Contact:	Dean Devoe	Location:	L51,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
P5279-01	ROCKAWAY-PARK	SOIL			12/13/24			12/13/24
			Mercury	7471B		12/16/24	12/16/24	
			Metals ICP-TAL	6010D		12/13/24	12/16/24	
P5279-02	ROCKAWAY-PARK	TCLP			12/13/24			12/13/24
			TCLP ICP Metals	6010D		12/18/24	12/20/24	
			TCLP Mercury	7470A		12/19/24	12/19/24	