



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Hit Summary Sheet
SW-846

SDG No.: P5279

Order ID: P5279

Client: Tully Construction Co., Inc.

Project ID: MTA Rockaway Park

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	RDL	Units
-----------	-----------	--------	-----------	---------------	---	-----	-----	-------

Client ID :

Total Concentration: 0.000

A

B

C

D



SAMPLE DATA

A

B

C

D

Report of Analysis

Client:	Tully Construction Co., Inc.		Date Collected:	12/13/24	
Project:	MTA Rockaway Park		Date Received:	12/13/24	
Client Sample ID:	ROCKAWAY-PARK		SDG No.:	P5279	
Lab Sample ID:	P5279-01		Matrix:	SOIL	
Analytical Method:	SW8082A		% Solid:	93.6	Decanted:
Sample Wt/Vol:	30.03	Units: g	Final Vol:	10000	uL
Soil Aliquot Vol:		uL	Test:	PCB	
Extraction Type:			Injection Volume :		
GPC Factor :	1.0	PH :			
Prep Method :	SW3541B				

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
PO108553.D	1	12/16/24 08:50	12/16/24 15:36	PB165646

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units(Dry Weight)
TARGETS						
12674-11-2	Aroclor-1016	0.0036	U	0.0036	0.018	mg/Kg
11104-28-2	Aroclor-1221	0.0068	U	0.0068	0.018	mg/Kg
11141-16-5	Aroclor-1232	0.0036	U	0.0036	0.018	mg/Kg
53469-21-9	Aroclor-1242	0.0036	U	0.0036	0.018	mg/Kg
12672-29-6	Aroclor-1248	0.0084	U	0.0084	0.018	mg/Kg
11097-69-1	Aroclor-1254	0.0029	U	0.0029	0.018	mg/Kg
37324-23-5	Aroclor-1262	0.0049	U	0.0049	0.018	mg/Kg
11100-14-4	Aroclor-1268	0.0037	U	0.0037	0.018	mg/Kg
11096-82-5	Aroclor-1260	0.0031	U	0.0031	0.018	mg/Kg
SURROGATES						
877-09-8	Tetrachloro-m-xylene	20.8		32 - 144	104%	SPK: 20
2051-24-3	Decachlorobiphenyl	19.6		32 - 175	98%	SPK: 20

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit



LAB CHRONICLE

OrderID:	P5279	OrderDate:	12/13/2024 12:03:00 PM
Client:	Tully Construction Co., Inc.	Project:	MTA Rockaway Park
Contact:	Dean Devoe	Location:	L51,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
P5279-01	ROCKAWAY-PARK	SOIL	PCB	8082A	12/13/24	12/16/24	12/16/24	12/13/24