

Hit Summary Sheet SW-846

SDG No.: P5279

Client: Tully Construction Co., Inc.

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	RDL	Units
Client ID: P5279-03	ROCKAWAY-PARK ROCKAWAY-PARI SOIL		Methylene Chloride	0.0050	J	0.0037	0.011	mg/Kg
			Total Voc :	0.0050				
P5279-03	ROCKAWAY-PARI SOIL		4-(2-Acetylamino-1-(trimethyls *	10.2	J	0	0	ug/Kg
			Total Tics :	10.2				
			Total Concentration:	10.2				



SAMPLE DATA

A

B

C

D

Report of Analysis

Client:	Tully Construction Co., Inc.		Date Collected:	12/13/24	
Project:	MTA Rockaway Park		Date Received:	12/13/24	
Client Sample ID:	ROCKAWAY-PARK		SDG No.:	P5279	
Lab Sample ID:	P5279-03		Matrix:	SOIL	
Analytical Method:	SW8260		% Solid:	94	
Sample Wt/Vol:	4.91	Units: g	Final Vol:	5000	uL
Soil Aliquot Vol:		uL	Test:	VOC-TCLVOA-10	
GC Column:	RXI-624	ID : 0.25	Level :	LOW	
Prep Method :					

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
VY020668.D	1		12/20/24 14:10	VY122024

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units(Dry Weight)
TARGETS						
75-71-8	Dichlorodifluoromethane	0.0018	U	0.0018	0.0054	mg/Kg
74-87-3	Chloromethane	0.0013	U	0.0013	0.0054	mg/Kg
75-01-4	Vinyl Chloride	0.00083	U	0.00083	0.0054	mg/Kg
74-83-9	Bromomethane	0.0011	U	0.0011	0.0054	mg/Kg
75-00-3	Chloroethane	0.0011	UQ	0.0011	0.0054	mg/Kg
75-69-4	Trichlorofluoromethane	0.00099	U	0.00099	0.0054	mg/Kg
76-13-1	1,1,2-Trichlorotrifluoroethane	0.0012	UQ	0.0012	0.0054	mg/Kg
75-35-4	1,1-Dichloroethene	0.00084	UQ	0.00084	0.0054	mg/Kg
67-64-1	Acetone	0.0068	UQ	0.0068	0.027	mg/Kg
75-15-0	Carbon Disulfide	0.0014	U	0.0014	0.0054	mg/Kg
1634-04-4	Methyl tert-butyl Ether	0.00073	UQ	0.00073	0.0054	mg/Kg
79-20-9	Methyl Acetate	0.0019	UQ	0.0019	0.0054	mg/Kg
75-09-2	Methylene Chloride	0.0050	J	0.0037	0.011	mg/Kg
156-60-5	trans-1,2-Dichloroethene	0.00091	UQ	0.00091	0.0054	mg/Kg
75-34-3	1,1-Dichloroethane	0.00068	UQ	0.00068	0.0054	mg/Kg
110-82-7	Cyclohexane	0.00075	U	0.00075	0.0054	mg/Kg
78-93-3	2-Butanone	0.0062	U	0.0062	0.027	mg/Kg
56-23-5	Carbon Tetrachloride	0.00094	U	0.00094	0.0054	mg/Kg
156-59-2	cis-1,2-Dichloroethene	0.00066	U	0.00066	0.0054	mg/Kg
74-97-5	Bromochloromethane	0.0026	UQ	0.0026	0.0054	mg/Kg
67-66-3	Chloroform	0.00073	U	0.00073	0.0054	mg/Kg
71-55-6	1,1,1-Trichloroethane	0.00084	U	0.00084	0.0054	mg/Kg
108-87-2	Methylcyclohexane	0.00094	U	0.00094	0.0054	mg/Kg
71-43-2	Benzene	0.00078	U	0.00078	0.0054	mg/Kg
107-06-2	1,2-Dichloroethane	0.00066	U	0.00066	0.0054	mg/Kg
79-01-6	Trichloroethene	0.00081	U	0.00081	0.0054	mg/Kg
78-87-5	1,2-Dichloropropane	0.00071	U	0.00071	0.0054	mg/Kg
75-27-4	Bromodichloromethane	0.00061	U	0.00061	0.0054	mg/Kg
108-10-1	4-Methyl-2-Pentanone	0.0047	U	0.0047	0.027	mg/Kg
108-88-3	Toluene	0.00073	U	0.00073	0.0054	mg/Kg

Report of Analysis

Client:	Tully Construction Co., Inc.			Date Collected:	12/13/24
Project:	MTA Rockaway Park			Date Received:	12/13/24
Client Sample ID:	ROCKAWAY-PARK			SDG No.:	P5279
Lab Sample ID:	P5279-03			Matrix:	SOIL
Analytical Method:	SW8260			% Solid:	94
Sample Wt/Vol:	4.91	Units:	g	Final Vol:	5000 uL
Soil Aliquot Vol:			uL	Test:	VOC-TCLVOA-10
GC Column:	RXI-624	ID :	0.25	Level :	LOW
Prep Method :					

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
VY020668.D	1		12/20/24 14:10	VY122024

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units(Dry Weight)
10061-02-6	t-1,3-Dichloropropene	0.00065	UQ	0.00065	0.0054	mg/Kg
10061-01-5	cis-1,3-Dichloropropene	0.00062	U	0.00062	0.0054	mg/Kg
79-00-5	1,1,2-Trichloroethane	0.00091	U	0.00091	0.0054	mg/Kg
591-78-6	2-Hexanone	0.0052	U	0.0052	0.027	mg/Kg
124-48-1	Dibromochloromethane	0.00070	U	0.00070	0.0054	mg/Kg
106-93-4	1,2-Dibromoethane	0.00086	U	0.00086	0.0054	mg/Kg
127-18-4	Tetrachloroethene	0.00096	U	0.00096	0.0054	mg/Kg
108-90-7	Chlorobenzene	0.00080	U	0.00080	0.0054	mg/Kg
100-41-4	Ethyl Benzene	0.00067	U	0.00067	0.0054	mg/Kg
179601-23-1	m/p-Xylenes	0.0015	U	0.0015	0.011	mg/Kg
95-47-6	o-Xylene	0.00076	U	0.00076	0.0054	mg/Kg
100-42-5	Styrene	0.00065	U	0.00065	0.0054	mg/Kg
75-25-2	Bromoform	0.00088	U	0.00088	0.0054	mg/Kg
98-82-8	Isopropylbenzene	0.00073	U	0.00073	0.0054	mg/Kg
79-34-5	1,1,2,2-Tetrachloroethane	0.0012	U	0.0012	0.0054	mg/Kg
541-73-1	1,3-Dichlorobenzene	0.00080	U	0.00080	0.0054	mg/Kg
106-46-7	1,4-Dichlorobenzene	0.00087	U	0.00087	0.0054	mg/Kg
95-50-1	1,2-Dichlorobenzene	0.00064	U	0.00064	0.0054	mg/Kg
96-12-8	1,2-Dibromo-3-Chloropropane	0.0017	UQ	0.0017	0.0054	mg/Kg
120-82-1	1,2,4-Trichlorobenzene	0.00086	U	0.00086	0.0054	mg/Kg
87-61-6	1,2,3-Trichlorobenzene	0.00084	U	0.00084	0.0054	mg/Kg

SURROGATES

17060-07-0	1,2-Dichloroethane-d4	50.2	50 - 163	100%	SPK: 50
1868-53-7	Dibromofluoromethane	44.7	54 - 147	89%	SPK: 50
2037-26-5	Toluene-d8	48.7	58 - 134	97%	SPK: 50
460-00-4	4-Bromofluorobenzene	32.3	29 - 146	65%	SPK: 50

INTERNAL STANDARDS

363-72-4	Pentafluorobenzene	177000	7.707
540-36-3	1,4-Difluorobenzene	313000	8.616
3114-55-4	Chlorobenzene-d5	250000	11.42
3855-82-1	1,4-Dichlorobenzene-d4	79000	13.353

TENTATIVE IDENTIFIED COMPOUNDS

Report of Analysis

Client:	Tully Construction Co., Inc.		Date Collected:	12/13/24	
Project:	MTA Rockaway Park		Date Received:	12/13/24	
Client Sample ID:	ROCKAWAY-PARK		SDG No.:	P5279	
Lab Sample ID:	P5279-03		Matrix:	SOIL	
Analytical Method:	SW8260		% Solid:	94	
Sample Wt/Vol:	4.91	Units: g	Final Vol:	5000	uL
Soil Aliquot Vol:		uL	Test:	VOC-TCLVOA-10	
GC Column:	RXI-624	ID : 0.25	Level :	LOW	
Prep Method :					

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
VY020668.D	1		12/20/24 14:10	VY122024

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units(Dry Weight)
1000373-43-5	4-(2-Acetylamino-1-(trimethylsilyl	10.2	J		13.9	ug/Kg

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

() = Laboratory InHouse Limit

A = Aldol-Condensation Reaction Products

LAB CHRONICLE

OrderID:	P5279	OrderDate:	12/13/2024 12:03:00 PM
Client:	Tully Construction Co., Inc.	Project:	MTA Rockaway Park
Contact:	Dean Devoe	Location:	L51,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
P5279-03	ROCKAWAY-PARK	SOIL	VOC-TCLVOA-10	8260D	12/13/24		12/20/24	12/13/24