

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: PARSONS Main of New York, Inc. Date Collected: 12/13/24 15:18

Project: Con Edison Non-MGP - Atlantic Avenue Date Received: 12/16/24

Client Sample ID: MW6-20241213-ADL SDG No.: P5291

Lab Sample ID: P5291-10DL Matrix: WATER

% Solid: 0

Parameter	Conc.	Qua.	DF MD	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Sulfate	38.7	D	2 0.06	6.00	mg/L		12/17/24 11:17	300.0

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits