

Report of Analysis

| | | | |
|-------------------|--|-----------------|----------------|
| Client: | Summit Environmental Technologies, LLC | Date Collected: | 12/05/24 10:35 |
| Project: | 24120686 | Date Received: | 12/20/24 |
| Client Sample ID: | 120524-89 | SDG No.: | P5370 |
| Lab Sample ID: | P5370-01 | Matrix: | WATER |
| | | % Solid: | 0 |

| Parameter | Conc. | Qua. | DF | MDL | LOQ / CRQL | Units | Prep Date | Date Ana. | Ana Met. |
|-----------|-------|------|-----|------|------------|-------|-----------|----------------|--------------|
| TOC | 5100 | D | 400 | 76.0 | 400 | mg/L | | 12/20/24 16:57 | SM 5310 B-14 |

Comments: _____

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N = Spiked sample recovery not within control limits