

## Report of Analysis

Client:	Weston Solutions	Date Collected:	12/20/24 14:15
Project:	Ft Meade Tipton Airfield Parcel RI - PO 0111169	Date Received:	12/21/24
Client Sample ID:	TAPIAL3-IDW-SOIL-122024-T1	SDG No.:	P5380
Lab Sample ID:	P5380-01	Matrix:	SOIL
		% Solid:	86.3

Parameter	Conc.	Qua.	DF	MDL	LOD	LOQ / CRQL	Units(Dry Weight)	Prep Date	Date Ana.	Ana Met.
Cyanide	0.23	U	1	0.049	0.23	0.28	mg/Kg	12/31/24 08:50	12/31/24 12:38	9012B
Ignitability	NO		1	0	0	0	oC		12/27/24 08:30	1030
pH	10.5	H	1	0	0	0	pH		12/27/24 09:55	9045D
Sulfide	3.70	J	1	2.15	5.77	11.5	mg/Kg	12/30/24 08:45	12/30/24 13:26	9034

Comments: pH result reported at temperature 20.2 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits