



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Hit Summary Sheet
SW-846

SDG No.: P5380

Order ID: P5380

Client: Weston Solutions

Project ID: Ft Meade Tipton Airfield Parcel RI - P

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	LOD	RDL	Units
-----------	-----------	--------	-----------	---------------	---	-----	-----	-----	-------

Client ID :

Total Concentration: 0.000

A

B

C

D



SAMPLE DATA

A

B

C

D

Report of Analysis

Client:	Weston Solutions		Date Collected:	12/20/24	
Project:	Ft Meade Tipton Airfield Parcel RI - PO 0111169		Date Received:	12/21/24	
Client Sample ID:	TAPIAL3-IDW-SOIL-122024-T1		SDG No.:	P5380	
Lab Sample ID:	P5380-01		Matrix:	SOIL	
Analytical Method:	SW8082A		% Solid:	86.3	Decanted:
Sample Wt/Vol:	30.06	Units: g	Final Vol:	10000	uL
Soil Aliquot Vol:		uL	Test:	PCB	
Extraction Type:			Injection Volume :		
GPC Factor :	1.0	PH :			
Prep Method :	SW3541B				

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
PO108769.D	1	12/26/24 08:30	12/26/24 14:10	PB165843

CAS Number	Parameter	Conc.	Qualifier	MDL	LOD	LOQ / CRQL	Units(Dry Weight)
TARGETS							
12674-11-2	Aroclor-1016	9.60	U	3.90	9.60	19.7	ug/kg
11104-28-2	Aroclor-1221	15.0	U	7.40	15.0	19.7	ug/kg
11141-16-5	Aroclor-1232	15.0	U	3.90	15.0	19.7	ug/kg
53469-21-9	Aroclor-1242	9.60	U	3.90	9.60	19.7	ug/kg
12672-29-6	Aroclor-1248	15.0	U	9.10	15.0	19.7	ug/kg
11097-69-1	Aroclor-1254	15.0	U	3.20	15.0	19.7	ug/kg
37324-23-5	Aroclor-1262	9.60	U	5.30	9.60	19.7	ug/kg
11100-14-4	Aroclor-1268	15.0	U	4.00	15.0	19.7	ug/kg
11096-82-5	Aroclor-1260	9.60	U	3.40	9.60	19.7	ug/kg
SURROGATES							
877-09-8	Tetrachloro-m-xylene	20.5		44 - 130		102%	SPK: 20
2051-24-3	Decachlorobiphenyl	16.1		60 - 125		80%	SPK: 20

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit



LAB CHRONICLE

OrderID:	P5380	OrderDate:	12/23/2024 9:50:00 AM
Client:	Weston Solutions	Project:	Ft Meade Tipton Airfield Parcel RI - PO 0111169
Contact:	Nathan Fretz	Location:	N31

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
P5380-01	TAPIAL3-IDW-SOIL-1 22024-T1	SOIL			12/20/24			12/21/24
			PCB	8082A		12/26/24	12/26/24	