

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

% Solid:

0

Fax: 908 789 8922

## **Report of Analysis**

Client: Summit Environmental Technologies, LLC Date Collected: 07/03/24 10:04 Project: 24120422 Date Received: 12/31/24 Client Sample ID: SDG No.: P5404 244672 Lab Sample ID: P5404-12 Matrix: WATER

Units Parameter DF MDL LOQ / CRQL **Prep Date** Date Ana. Ana Met. Conc. Qua. TOC 01/08/25 13:27 SM 5310 B-14 10.1 0.19 1.00 mg/L

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits