

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Summit Environmental Technologies, LLC Date Collected: 11/05/24 06:17 Project: 24120422 Date Received: 12/31/24 Client Sample ID: SDG No.: P5404 244680 Lab Sample ID: P5404-20 Matrix: WATER % Solid: 0

Parameter	Conc.	Qua.	DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
TOC	9.70	Н	1 0.19	1.00	mg/L		01/04/25 06:02	2 SM 5310 B-14

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits