

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Summit Environmental Technologies, LLC Date Collected: 12/04/24 08:50

Project: 24120281 Date Received: 12/31/24

Client Sample ID: 002-OUTFALL SDG No.: P5405

Lab Sample ID: P5405-01 Matrix: WATER

% Solid: 0

| Parameter | Conc. (| Qua. | DF MDL | LOQ / CRQL | Units | Prep Date | Date Ana. | Ana Met. |
|-----------|---------|------|--------|------------|-------|-----------|----------------|--------------|
| TOC | 5.90 | Н | 1 0.19 | 1.00 | mg/L | | 01/04/25 06:27 | SM 5310 B-14 |

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits