

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

2412-0430-003

## **Report of Analysis**

Client: Summit Environmental Technologies, LLC Date Collected: 02/17/24 09:37

Project: 24121544 Date Received: 12/31/24

Client Sample ID: Lab Sample ID: P5407-03 Matrix: WATER

> % Solid: 0

P5407

SDG No.:

Parameter	Conc. Q	Qua.	DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
TOC	2.60	Н	1 0.19	1.00	mg/L		01/08/25 20:18	SM 5310 B-14

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits