

Report of Analysis

| | | | |
|-------------------|--|-----------------|----------------|
| Client: | Summit Environmental Technologies, LLC | Date Collected: | 02/17/24 11:32 |
| Project: | 24121544 | Date Received: | 12/31/24 |
| Client Sample ID: | 2412-0430-007 | SDG No.: | P5407 |
| Lab Sample ID: | P5407-07 | Matrix: | WATER |
| | | % Solid: | 0 |

| Parameter | Conc. | Qua. | DF | MDL | LOQ / CRQL | Units | Prep Date | Date Ana. | Ana Met. |
|-----------|-------|------|----|------|------------|-------|-----------|----------------|--------------|
| TOC | 24.8 | HOR | 1 | 0.19 | 1.00 | mg/L | | 01/09/25 00:03 | SM 5310 B-14 |

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits