

В

C

SAMPLE DATA



284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Summit Environmental Technologies, LLC Date Collected: 12/02/24 00:00

 Project:
 24120833
 Date Received:
 12/31/24

 Client Sample ID:
 244758
 SDG No.:
 P5409

Lab Sample ID: P5409-01 Matrix: WATER

% Solid: 0

Parameter	Conc. Qua	. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
TOC	3.40 H	1 0.19	1.00	mg/L		12/31/24 13:5	54 SM 5310 B-14

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits







LAB CHRONICLE

12/31/2024 10:48:00 AM

P5409 OrderID: OrderDate:

Summit Environmental Technologies, LLC 24120833 Client: Project: K11

Jennifer Woolf Location: Contact:

LabID	ClientID	Matrix	Test	Method Sai	mple Date	Prep Date	Anal Date	Received
P5409-0	1 244758	WATER		12/02/24			12/31/24	
			TOC	SM5310B	00:00		12/31/24	
			100	31133100			13:54	