

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Summit Environmental Technologies, LLC Date Collected: 12/10/24 12:33

Project: 24120694 Date Received: 12/31/24

Client Sample ID: OUTFALL-003 SDG No.: P5410

Lab Sample ID: P5410-01 Matrix: WATER

% Solid: 0

Parameter	Conc. Qu	ıa. DF MDL	LOQ / CRQL	Units	Prep Date		Ana Met.
TOC	12.7 H	I 1 0.19	1.00	mg/L		01/09/25 00:29	SM 5310 B-14

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits