

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 01/03/25 10:16 Project: Summit Gas District Date Received: 01/03/25 Client Sample ID: 60409 SDG No.: Q1008 Lab Sample ID: Q1008-07 Matrix: WATER % Solid: 0

Parameter	Conc. Qua	a. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
рН	6.26 H	1 0	0	рН		01/03/25 14:4	7 9040C

Comments: pH result reported at temperature 20.3 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits