

## Duplicate Sample Summary

|                                         |                                           |
|-----------------------------------------|-------------------------------------------|
| <b>Client:</b> Tully Environmental, Inc | <b>SDG No.:</b> Q1012                     |
| <b>Project:</b> Transfer Station-SPDES  | <b>Sample ID:</b> Q1012-04                |
| <b>Client ID:</b> 002 35TH AVE (DEC)DUP | <b>Percent Solids for Spike Sample:</b> 0 |

| Analyte | Units | Acceptance<br>Limit | Sample<br>Result | Conc.<br>Qualifier | Duplicate<br>Result | Conc.<br>Qualifier | Dilution<br>Factor | RPD/<br>AD | Qual | Analysis<br>Date |
|---------|-------|---------------------|------------------|--------------------|---------------------|--------------------|--------------------|------------|------|------------------|
| TSS     | mg/L  | +/-5                | 35.5             |                    | 36.8                |                    | 1                  | 3.6        |      | 01/07/2025       |